TEXAS AVENUE CORRIDOR STUDY PROPERTY INVENTORY SURVEY FORM GROUP 3

Property ID:	R44577

Property Information

property address:	118 HARDY		34/35
legal description:	SUBER #2, LOT 7,8,22 & 23 (PT:	S OF)	n vand
owner name/address:	KASSEM, ADNAN S		
	1317 MULLINS LOOP S		
	COLLEGE STATION, TX 7784		
	w/9		
land use category:	vecant	type of business:	u f
current zoning:			
lot area (square feet):		frontage along Texas Av	venue (feet):
lot depth (feet):			
property conforms to:	□ min. lot area standards	□ min. lot depth standards	min, lot width standards
Improvements			
# of buildings:	building height (feet)	# of stor	ries:
	cify):		
building/site condition	:		
buildings conform to n	ninimum building setbacks:	□ yes □/no (if no, sp	pecify) front & Side
approximate constructi	ion date: accessible to th	ne public: 🗆 yes 💆 no	÷
possible historic resour	rce: □ yes prno sidev	valks along Texas Avenue:	o yes ono N (9
other improvements:	yes in (specify) <u>With</u>	1 Eura	
,	*	(pipe fences, decks, carp	orts, swimming pools, etc.)
Freestanding Signs			
□ yes pano		🗆 dilap	idated □ abandoned □ in-use
# of signs:	type/material of sign:		
overall condition (spec			
removal of any dilapida	ated signs suggested? yes r	□ no (specify)	
Off-street Parking			
			ailable off-street spaces:
	concrete other		
space sizes:	suf	ficient off-street parking for	existing land use: yes no
end islands or bay divid	lers: 🗆 ves 🗆 no:		landscaped islands: mives in no.

Curb Cuts on Texas Avenue
ow many:
f yes, which ones:
neet adjacent separation requirements: 🗆 yes 🗆 no 💮 meet opposite separation requirements: 🗆 yes 🗅 r
Landscaping
yes no (if none is present) is there room for landscaping on the property? yes no
comments:
Outside Storage
·
yes pho (specify)(Type of merchandise/material/equipment stored)
dumpsters present: yes no are dumpsters enclosed: yes no 9
<u>Miscellaneous</u>
is the property adjoined by a residential use or a residential zoning district?
yes no (circle one) residential use residential zoning district
is the property developable when required buffers are observed?
if not developable to current standards, what could help make this a developable property?
accessible to alley: yes your no
Other Comments:
vacant lot - whenely rundown - has bean
respected littered - above present
& Broken slab on property
<u> </u>